

REPLACEMENT PARTS (REVISION 2)

FOR MODEL # E50S, E80S, E120S, E150S

#	PARTS	ITEM #
1	UV Lamp	
	E50S (50 WATT)	FL-2538-IP
	E80S (80 WATT)	FL-2997-IP
	E120S (120 WATT)	FL-2998-IP
	E150S (150 WATT)	FL-2999-IP
2	4-Pin Lamp Connector	709-1S
3	Lamp Spacer (Optional)	960503
4	Black Retaining Nut	411000
10	QSM/Union Gasket	410016Z-AQ
16	Reducer 2.5"x2"	437292
9	Quartz Sleeve	
	E50S (50 WATT)	FL-QZ175-IP
	E80S (80 WATT)	FL-QZ176-IP
	E120S (120 WATT)	FL-QZ165-IP
	E150S (150 WATT)	FL-QZ167-IP
11	UV Sterilizer Housing – with unions and quartz sleeve module (REVISION 2 BODY STYLE)	
	E50S (50 WATT)	960559
	E80S (80 WATT)	960560
	E120S (120 WATT)	960561
	E150S (150 WATT)	960562

#	KITS	ITEM #
	Quartz Sleeve Module – QSM	
	Includes 5, 8	523382-AQ
8	Quartz Sleeve Gasket	960533

Union Assembly

	Includes 4, 10, 13, 14	960477
--	------------------------	--------

Ballast Assembly -50/60 Hz

	Includes 2, 3	—
	50W, 80W, 120W (120/230VAC)	20105-MV
	150W (120VAC)	202150-1
	150W (230VAC)	202150-2

Seal Kit – 50, 80, 120, 150W

	Items 8, 10	523383-AQ
--	-------------	-----------

NOTE: Seals must be changed every year.

